

L Number	Hits	Search Text	DB	Time stamp
1	3043	(solder adj ball\$2) and(pad\$2) and (electrode\$2 wiring\$2) and(line\$2)	USPAT; US-PGPUB	2004/05/28 23:34
2	1468	( photo\$1electric image light photo)and ((solder adj ball\$2) and(pad\$2) and (electrode\$2 wiring\$2) and(line\$2))	USPAT; US-PGPUB	2004/05/28 23:33
3	17	( photo\$1electric image light photo)adj2(conver\$4)and ((solder adj ball\$2) and(pad\$2) and (electrode\$2 wiring\$2) and(line\$2))	USPAT; US-PGPUB	2004/05/28 23:34
4	53	(solder adj ball\$2) and(pad\$2) and (electrode\$2 wiring\$2) and(line\$2)	EPO; JPO; DERWENT	2004/05/28 23:33
5	0	( photo\$1electric image light photo)adj2(conver\$4)and ((solder adj ball\$2) and(pad\$2) and (electrode\$2 wiring\$2) and(line\$2))	EPO; JPO; DERWENT	2004/05/28 23:33
6	0	( photo\$1electric image light photo)and (( photo\$1electric image light photo)adj2(conver\$4)and ((solder adj ball\$2) and(pad\$2) and (electrode\$2 wiring\$2) and(line\$2)))	EPO; JPO; DERWENT	2004/05/28 23:35
7	4071	(solder adj ball\$2) and(pad\$2) and (electrode\$2 wiring\$2)	USPAT; US-PGPUB	2004/05/28 23:35
8	22	( photo\$1electric image light photo)adj2(conver\$4)and ((solder adj ball\$2) and(pad\$2) and (electrode\$2 wiring\$2) )	USPAT; US-PGPUB	2004/05/28 23:34
9	5	(( photo\$1electric image light photo)adj2(conver\$4)and ((solder adj ball\$2) and(pad\$2) and (electrode\$2 wiring\$2) )) not (( photo\$1electric image light photo)adj2(conver\$4)and ((solder adj ball\$2) and(pad\$2) and (electrode\$2 wiring\$2) and(line\$2)))	USPAT; US-PGPUB	2004/05/28 23:34
10	726	(solder adj ball\$2) and(pad\$2) and (electrode\$2 wiring\$2)	EPO; JPO; DERWENT	2004/05/28 23:35
11	37	( photo\$1electric image light photo)and ((solder adj ball\$2) and(pad\$2) and (electrode\$2 wiring\$2) )	EPO; JPO; DERWENT	2004/05/28 23:35